



Address: 1995 Eidson Dr., Deland, FL 32724
 Phone: (386) 848-4466
 Email: TradewindsCoach@gmail.com
 Web: www.TradewindsCoach.com

Date	Invoice #
9/28/2026	5117

Year: 2004
 Make: Prevost
 Model: Featherlite H3-45
 VIN: 2PCV3349831014499
 Mileage: 34,904

Bill To:
 Auto World of Conway

Terms
Due on receipt

Item	Quantity	Description	U/M	Rate	Amount
ES	1	Main engine oil service. Drain & replace fluid. Change oil & fuel filters. Dispose of oil & filters.		595.00	595.00T
EAF	1	R/R main engine air filter.		298.82	298.82T
CDF	1	Coolant system drain and flush		1,200.00	1,200.00T
CF	1	Coolant filter		54.77	54.77T
FGB	1	Service Fan Gear Box, Change Oil.		150.00	150.00T
Syn Tran	1	Synthetic transmission service. Drain & replace fluid. Change filters. Dispose of oil & filters.		695.00	695.00T
Diff	1	Change differential fluid.		500.00	500.00T
AD	2	R/R air dryer cartridge		160.00	320.00T
Valve Pack w/G...	1	Valve Pack with Governor, Purge		286.03	286.03T
Lube	1	Lube Chassis		250.00	250.00T
PSF	1	Power steering filter replace and fluid fill		225.00	225.00T
GS	1	Generator service. Drain & replace oil. Change oil & fuel filters. Dispose of oil & filters.		325.00	325.00T
AS	1	Aqua hot service		250.00	250.00T
SEP	1	R/R accessories air filter element		228.08	228.08T
BRF	8	Part: Brass Fitting		12.52	100.16T
1L	5	Remote breaker control inop - BIM box 24VDC fuse blows. Traced issue back to bad DC to DC converter that powers the inverter. Replaced DC to DC converter power to & from all transformers OK. No communication to square D powerlink. Found faulty 120Vac fuse holder. Replaced 24V & 120V fuse holders on BIM box. Tested operation, OK.		160.00	800.00T
4AMP Glass Fu...	4	4AMP Glass Fuse		6.74	26.96T
DC DC Convert...	1	DC Converter 12V 100W		120.78	120.78T
Fuse Holder Pa...	2	Fuse Holder Panel Mount 10A, Recessed Mount Drawer Fuse Holder 30mm		8.085	16.17T
SH	1	Shipping & handling		15.11	15.11T
SH	1	Shipping & handling		8.15	8.15T
2L	1	AquaHot broken hose at goose neck - Repaired hose to overflow new cap.		160.00	160.00T
Radiator Cap #7...	1	Radiator Cap		7.14	7.14T
Transfer Fluid ...	2	Transfer Fluid Red, 1 Gal		57.79	115.58T

Subtotal
Sales Tax ()
Total
Payments/Credits
Balance Due



Address: 1995 Eidson Dr., Deland, FL 32724
 Phone: (386) 848-4466
 Email: TradewindsCoach@gmail.com
 Web: www.TradewindsCoach.com

Bill To:
 Auto World of Conway

Date	Invoice #
9/28/2026	5117

Year: 2004
 Make: Prevost
 Model: Featherlite H3-45
 VIN: 2PCV3349831014499
 Mileage: 34,904

Terms
Due on receipt

Item	Quantity	Description	U/M	Rate	Amount
3L		PM sheet completed. - sent to customer & moved forward with recommended services		0.00	0.00T
4L	24	Drain coolant from generator, unhooked exhaust & unwired unit. Remove generator. Remove sound down & clean generator bay. Install new sound down & generator.		160.00	3,840.00T
Insulation Pins ...	40	Insulation Pins & Keeper Aluminum 2.5"		1.06	42.40T
Vinyl/Foam Ins...	2	Vinyl/Foam Insulation		258.63	517.26T
Airbag Engine ...	4	Airbag Engine Mount		241.00275	964.01T
SH	1	Shipping & handling		34.04	34.04T
5L	12	Service all Cruis Airc: FWD - Lo PS code. Isolate & check unit operation. Found flex hoses leaking. R/R hose. Remove hot gas bypass valve. Replace 5/16 elbow on liquid line. Evac & charge. NOTE - during a test drive AC unit failed to Hi PS, however was never able to duplicate Hi PS fault code again. Freon charge is correct - suspect possible cavitation of exhaust air during test drive. Mid L AC showing Lo PS. Found leak at hot gas bypass valve. Remove bypass valve & test. Unit ran okay for a several days, but Lo PS eventually came back. Further isolate & identify leaks. Found liquid line flex hose leaking. R/R both flex hoses. Evac & charge. During testing thermostat would no longer adjust temperature. Check connections; okay. R/R thermostat; okay. Mid R AC showing Lo PS. Open up unit & check for leaks; nothing found. Top off freon & monitor operation. Found compressor not shutting down when unit cycles off. Troubleshoot & found a bad crydom replay. R/R relay & test operation. After AC units were running & cooling found that the AFT AC (previously thought to be good) was not cooling as efficiently as others. Open up unit & remove hot gas bypass valve. Top off freon charge.		160.00	1,920.00T
Freon - RS-44B	14	Freon RS44B	lb	35.12	491.68T
SMXII Control ...	1	Control Display/Keypad		266.37	266.37T
Flex Line #4 - Hi	2	Cruise Air Flex Line #4 - Hi, 4FT		101.25	202.50T
Flex Line #8 - Lo	2	Cruise Air Flex Line #8 - Lo, 4FT		182.25	364.50T
1/2" x 6' Pipe Ins	3	1/2" x 6' Pipe Ins		9.68	29.04T

Subtotal
Sales Tax ()
Total
Payments/Credits
Balance Due



Address: 1995 Eidson Dr., Deland, FL 32724

Phone: (386) 848-4466

Email: TradewindsCoach@gmail.com

Web: www.TradewindsCoach.com

Bill To:

Auto World of Conway

Date	Invoice #
9/28/2026	5117

Year: 2004

Make: Prevost

Model: Featherlite H3-45

VIN: 2PCV3349831014499

Mileage: 34,904

Terms
Due on receipt

Item	Quantity	Description	U/M	Rate	Amount
Crydom A2475	1	Crydom Solid State Relay		135.28	135.28T
6L	0.5	R/R shore cord plug - Current shore cord plug overheating. Replaced.		160.00	80.00T
Hubbell HBL94...	1	Hubbell Plug, Angle, 3-Pole, 4-Wire, 50-Amp, 125/250V		92.34	92.34T
7L	2	R/R chassis batteries.		160.00	320.00T
1131MF	4	Battery 1131MF		186.65	746.60T
8L	1.5	Bay 5 rub rail light inop D/S - Dismantle rub rail, look out old bulb. Made new connections for new bulb. Put back together.		160.00	240.00T
Bulb H3-W27	1	Bulb H3-W27-CB White		20.18	20.18T
9L	0.5	Dinette & stateroom aft cabinet lights inop - R/R bulbs. Reassembled & tested.		160.00	80.00T
Mini Bulb 194	2	Mini Bulb		4.87	9.74T
10L	0.25	Shade master out of sync - Put all shades down. Cut shade breaker. Waited & turned breaker back on.		160.00	40.00T
11L	1.25	Fresh tank gauge in Bay is pulsating - Tested volts & everything was looking good. Gauge flickers trying to be correct. Seems gauge is shot & needs to be replaced. Replaced with refurbish gauge. Filled tank & configured tanks levels. NOTE - TANKS WILL BE DUMPED/FILLED AND GAUGES RECHECKED PRIOR TO PICKUP		160.00	200.00T
TS3003	1	Tank sentry monitor		687.78	687.78T
Discount		Discount - refurbished part		-275.11	-275.11
12L	0.25	P/S forward docking light inop - Replaced old front P/S docking light with new.		160.00	40.00T
Sealed Beam #...	1	Sealed Beam #H9415		26.39	26.39T
13L	7.5	Toll window inop - Took out old mounting bracket. Drilled out rivets. Took out motor. Put in new motor & new bolts. Put mount back on. Used silicone conditioner on seal.		160.00	1,200.00T

Subtotal
Sales Tax ()
Total
Payments/Credits
Balance Due



Address: 1995 Eidson Dr., Deland, FL 32724

Phone: (386) 848-4466

Email: TradewindsCoach@gmail.com

Web: www.TradewindsCoach.com

Bill To:

Auto World of Conway

Date	Invoice #
9/28/2026	5117

Year: 2004

Make: Prevost

Model: Featherlite H3-45

VIN: 2PCV3349831014499

Mileage: 34,904

Terms
Due on receipt

Item	Quantity	Description	U/M	Rate	Amount
Win Lift Mtr #7...	1	Win Lift Mtr #742-150		50.12	50.12T
14L	1.25	Aft vanity fixture issue: bulbs broke off, repair as needed - Light sockets broken inside fixture replaced. Installed new bulbs. Tested vanity light, OK.		160.00	200.00T
G9 Socket, Cera...	3	G9 Socket, Ceramic		16.86	50.58T
G9 Halogen Bul...	3	G9 Halogen Bulb 40Q 120V T4		12.14	36.42T
15L	0.25	Locate & Test door code - Located code 11311 & it works.		160.00	40.00T
17L	0.25	R/R windshield washer bucket bungee - Removed old broken bungee's & replaced with new.		160.00	40.00T
Rubber Tie Do...	2	Rubber Tie Down		16.63	33.26T
18L	1	P/S windshield washer squirter - Took out dash, accessed panel. Located broken off front coupler. Put in new bumper coupler for tube with rubber washer & put dash back together.		160.00	160.00T
Adapter, Right ...	1	Adapter, Right		2.592	2.59T
WSH FL RUB ...	1	WSH FL RUB BK .187x1x.125 (M4.#8)		1.02	1.02T
19L	1	Fresh tank slowly going down on drain gauge - Repenetrated fresh tank & gauge stopped draining.		160.00	160.00T
1/4" OD x 36" ...	1	1/4" OD x 36" Long Nylon Tube		15.83	15.83T
Collet Cover for...	1	Collect Cover for 1/4" Tubing Connectors		4.59	4.59T
Stainless Steel ...	1	Stainless Steel Tube Weight		22.77	22.77T
Union for 1/4" ...	1	Union for 1/4" OD Tubing		19.77	19.77T
Tank Insert Fitti...	1	Tank Insert Fitting w/ 1-1/4" SCH 80 PVC		200.76	200.76T
1/4" Urethane T...	10	1/4" Urethane Tubing, FT	ft	5.14315	51.43T

Subtotal
Sales Tax ()
Total
Payments/Credits
Balance Due



Address: 1995 Eidson Dr., Deland, FL 32724
Phone: (386) 848-4466
Email: TradewindsCoach@gmail.com
Web: www.TradewindsCoach.com

Bill To:
 Auto World of Conway

Date	Invoice #
9/28/2026	5117

Year: 2004
Make: Prevost
Model: Featherlite H3-45
VIN: 2PCV3349831014499
Mileage: 34,904

Terms
Due on receipt

Item	Quantity	Description	U/M	Rate	Amount
20L	32	R/R all TVs. Pull stateroom & salon TVs. Build mount for salon location for customer supplied TV. Hang TV on mount. Fab trim pieces for gaps. Use original trim piece for material. Install converter to get picture on TV. Remove bay TV. Build out entertainment cabinet. Make with close-out (able to remove). . Install stateroom TV (also customer provided). Run HDMI's, attach optical to Bose. Signal converted from analog to digital for picture. Reassemble stateroom & test.		160.00	5,120.00T
RCA to HDMI ...	3	RCA to HDMI Converter, Composite to HDMI Adapter Support		12.14	36.42T
HDMI3	3	Part: 3' HDMI		7.99	23.97T
Plywood, 18mm...	1	Plywood, 18mm 4x8 B/BB Light		17.63	17.63T
Plywood, 12mm,...	1	Plywood, 12mm, B/BB, Light Poplar		19.2071	19.21T
Laminate, Black...	1	Laminate: Solid Black 4x8 VT		21.087	21.09T
HDMI10	2	Part: 10' HDMI		12.99	25.98T
Digital Audio C...	1	Digital Optical Audio Cable, 10FT		8.77	8.77T
Fixed TV Wall ...	1	Fixed TV Wall Mount Bracket, Low Profile		20.51	20.51T
ETN TR ST GF...	1	ETN TR ST GFCI BK		34.39	34.39T
HDMI Wall Pla...	1	HDMI Wall Plate 1 Port - Flat [Black]		15.40	15.40T
10 Amp 22mm ...	2	10 Amp 22mm Momentary Push Button Switch		19.62	39.24T
Foldable Samsu...	1	Foldable Samsung Wireless Charger Stand		21.29	21.29T
21L	3.75	Ceiling & stateroom carpet fiber optics inop - Replaced bulb in state room carpet illuminator. Could not repair ceiling illuminator. Replaced with rebuilt illuminator; tested. OK.		160.00	600.00T
Sylvania HQI-S...	1	Sylvania HQI-SE150/NDX Light Bulb		98.47	98.47T
Electrical	1	Rebuilt illuminator		500.00	500.00T
SH	1	Shipping & handling		4.99	4.99T
22L	8.25	R/R dash head unit - R/R dash head unit. Remove all components to old system. Relocate all wiring from step well to dash. Install & secure new head unit. Split B/U camera signal to new screen. Put sat antennas in upper windshield area. New dish cubby close out.		160.00	1,320.00T
Pioneer DMH-...	1	Pioneer DMH-WT8600NEX 10.1" HD Touchscreen Floating Display Car Stereo		1,650.00	1,650.00T
6' RCA A/V Pa...	1	6' RCA A/V Patch Cable		8.10	8.10T
RCA Splitter, C...	1	RCA Splitter, Composite Video		25.64	25.64T

Subtotal
Sales Tax ()
Total
Payments/Credits
Balance Due



Address: 1995 Eidson Dr., Deland, FL 32724
 Phone: (386) 848-4466
 Email: TradewindsCoach@gmail.com
 Web: www.TradewindsCoach.com

Bill To:
 Auto World of Conway

Date	Invoice #
9/28/2026	5117

Year: 2004
 Make: Prevost
 Model: Featherlite H3-45
 VIN: 2PCV3349831014499
 Mileage: 34,904

Terms
Due on receipt

Item	Quantity	Description	U/M	Rate	Amount
Plywood, 12mm, ...	1	Plywood, 12mm, B/BB, Light Poplar		5.0545	5.05T
Laminate, Black...	1	Laminate: Solid Black 4x8 VT		4.7925	4.79T
23L	16	Replaced steer air bags. Replaced tag bags. Replaced drive bags. Brake & suspension inspection completed.		160.00	2,560.00T
Air Tank Drain ...	8	Air Tank Drain Valve 1/4"		10.80	86.40T
Air Spring Assy...	4	Air Spring Assy. #630260		249.98	999.92T
Air Spring 12" ...	4	Air Spring 12" w/Tank		333.79	1,335.16T
Airbag Engine ...	4	Airbag Engine Mount #09MNTAIR4		241.00275	964.01T
24L	24	Perform chassis work as found during inspection. STEER: Upper & lower control arms. Drag link end, center rod end, side rods, tie rods, red sway bar bushings, oil bath caps, caliper boots. TAG: Brake calipers. DRIVE: sway bar bushings, caliper boots.		160.00	3,840.00T
Rod End LH #6...	1	Rod End LH #661200		336.18	336.18T
Caliper RH, Ass...	1	Caliper RH, Assy		877.49	877.49T
Caliper LH Ass...	1	Caliper LH Assy		877.49	877.49T
Seal Kit #N889...	2	Seal Kit		340.74	681.48T
Lower V Link L...	1	Lower V Link LH Long Arm to Front		957.75	957.75T
Lower V-Link ...	1	Lower V-Link RH Long Arm to Front		957.75	957.75T
Upper V-Link ...	2	Upper V-Link with Lub. Points		698.31	1,396.62T
Tie Rod End Ri...	1	Tie Rod End Right Hand Thread		168.76	168.76T
Tie Rod End Ri...	1	Tie Rod End Left Hand Thread		168.76	168.76T
Tie Rod, Center...	1	Tie Rod, Center		248.73	248.73T
Tie Rod IFS19...	2	Tie Rod IFS19K #661182		276.72	553.44T
Hub Cap-Oil #6...	4	Hub Cap-Oil		149.48	597.92T
Torque Rod #66...	2	Torque Rod #660993		217.27	434.54T
Bushing Polyur ...	16	Bushing Polyurethane Red		6.91	110.56T
Motorcoach Ali...	1	Motorcoach Alignment		1,000.00	1,000.00T
25L	12	Paint repair damage on passenger side of coach that occurred during sand/buff.		160.00	1,920.00T
26L	15	Paint repair damage on passenger side of coach - halo area above rear fender.		160.00	2,400.00T
27L	28	Paint repair on front end of coach.		160.00	4,480.00T
Paint & Body	1	Paint & body supplies		1,000.00	1,000.00T

Subtotal
Sales Tax ()
Total
Payments/Credits
Balance Due



Address: 1995 Eidson Dr., Deland, FL 32724
 Phone: (386) 848-4466
 Email: TradewindsCoach@gmail.com
 Web: www.TradewindsCoach.com

Bill To:
 Auto World of Conway

Date	Invoice #
9/28/2026	5117

Year: 2004
 Make: Prevost
 Model: Featherlite H3-45
 VIN: 2PCV3349831014499
 Mileage: 34,904

Terms
Due on receipt

Item	Quantity	Description	U/M	Rate	Amount
28L	6	Replace driver console burl wood top w/ corian top. Cut cup holder in to top.		160.00	960.00T
Stainless Drink ...	1	Stainless Drink Holder with Drain		6.79	6.79T
29L	6	Template, fabricate & install new mirror plex ceiling in shower. Install lights.		160.00	960.00T
30L	4	Reglue loose mirror plex, vitracore, accent lights. Adjust doors in coach as needed. Replace push button knobs in 3 locations as needed.		160.00	640.00T
Push Button Lat...	3	Push Button Latch Body Only		8.19	24.57T
31L	1.5	R/R belts on main engine. R/R idler pulley assembly.		160.00	240.00T
5100495	2	Belt - Poly-Rib		78.94	157.88T
BX77	4	Part: Belt		45.75	183.00T
V-Belt Poly V1...	1	V-Belt, Poly V12		73.36	73.36T
Idler Pulley Ass...	1	Idler Pulley Assy		1,351.15	1,351.15T
SH	1	Shipping & handling		162.42	162.42T
32L		Supply spare filters & missing roadside equipment.		0.00	0.00T
Fuel/Water Filte...	1	Fuel/Water Separator		46.43	46.43T
WIX Filter - 57...	1	WIX Filter		131.13	131.13T
33120331	1	Fuel filter		39.99	39.99T
Fleetguard Fuel ...	1	Fleetguard Fuel/Water Separator Spin On		112.10	112.10T
Coolant Filter-...	1	Coolant Filter		21.74	21.74T
Oil Filter-51971	2	Oil Filter		31.33	62.66T
Fuel Filter-WIX...	1	Fuel Filter		14.62	14.62T
Oil Filter-WIX-...	1	Oil Filter		10.71	10.71T
33L	2.25	Install black flooring cover in bay 4 on driver & passenger side of coach.		160.00	360.00T
34L	1	Replace rivet in DS salon slideout. Seal voids w/ silicone. Drill small holes in slideout panel.		160.00	160.00T

Subtotal
Sales Tax ()
Total
Payments/Credits
Balance Due



Address: 1995 Eidson Dr., Deland, FL 32724

Phone: (386) 848-4466

Email: TradewindsCoach@gmail.com

Web: www.TradewindsCoach.com

Bill To:

Auto World of Conway

Date	Invoice #
9/28/2026	5117

Year: 2004

Make: Prevost

Model: Featherlite H3-45

VIN: 2PCV3349831014499

Mileage: 34,904

Terms
Due on receipt

Item	Quantity	Description	U/M	Rate	Amount
35L	1.75	Remove panel from passenger seat. Convert to small storage area.		160.00	280.00T
36L	2.5	Remove slideout roller wheel mechanisms from coach. R/R wheels. Adjust sensors. Install & test.		160.00	400.00T
CB-041605-60...	6	Slideout Roller		22.04	132.24T
37L	3	R/R salon slideout awning arms.		160.00	480.00T
Slideout Hardw...	2	Slideout Hardware		58.04	116.08T
38L	0.5	R/R wiper blades		160.00	80.00T
ANCO 53-22 W...	2	Wiper Refill Blades		40.49	80.98T
Detail Interior	1	Interior Detail		250.00	250.00T
Goodwill	1	Goodwill - Labor discount		-250.00	-250.00T
Detail Bays	1	Detail Bays		200.00	200.00T
Goodwill	1	Goodwill - Labor discount		-200.00	-200.00T
Shop Supplies	1	Shop Supplies		214.65	214.65T

THANK YOU FOR YOUR BUSINESS.

Payment Terms Accepted

Wire: Banking instructions available upon request

Personal/Business Check: Made payable to Tradewinds Coach

Credit Card: All major credit cards are accepted with a 3% convenience fee.

Subtotal	\$66,228.29
Sales Tax ()	\$0.00
Total	\$66,228.29
Payments/Credits	\$0.00
Balance Due	\$66,228.29