



PDI

1. VEHICLE HISTORY

LINE#	VIN# 2PCV3349831014499	Date: 10/2026	Passed	Needs Repair	Needs Replace	Complete	NOTES
	Mileage: 34,943						
	Vin history search						
	Service recalls						
	Verified maintaince	X					

2. ROAD TEST

		Passed	Needs Repair	Needs Replace	Complete	NOTES
	Engine starts and idles properly	X				
	Alternator output good (chassis & house)	X				
	Engine accelerates normal					
	Cruise control operates					
	Engine sounds normal (cold/hot & high/low speed)					
	Transmission shifts normal (cold/hot)					
	Transmission operation noise normal					
	Drive axle operation noise normal					
	Tag axle operates properly					
	Steers normally (response, centering & free play)					
	Body and suspension - squeaks & rattles					
	Shocks operate properly					
	Brakes / ABS operate properly (pulling, dragging, spongie)					
	Gauges operate properly					
	No abnormal wind noise					

RO # :15096
MILEAGE: 34,943

COACH # : 4499

2

3. CHASSIS AND SERVICES		Passed	Needs Repair	Needs Replace	Complete	NOTES
	Tire dot dates (within 5 years)	X				
	House battery dates (within 3 years)	X				Interstate batteries 3/23
	Chassis battery dates (within 3 years)	X				26-Aug
	Check PM service date / Last serviced:	X				9/14/2026
	Genreator service (21 point inspection)	X				9/26 @397hrs
	Generator battery date (if equipped)	n/a				
	Aquahot Service (37 point inspection)	X				9/21/2026
	Transmission service date	X				
4. VEHICLE EXTERIOR						NOTES
	4A - Body Panels and Bumpers	Passed	Needs Repair	Needs Replace	Complete	
	No evidence of prior Flood, Fire, Major damage	X				
	Body panel inspection (secure,scratches, flawed paint)		X			panel under DR trap window rattles / scuffs DR rear corner
	Bumper/Fascia inspection (secure,scratches,flawed paint)		X			scratches on rear bumper
	4B - Trim / Weather Stripping	Passed	Needs Repair	Needs Replace	Complete	NOTES
	Body trim Sealed and secure	X				
	Front grill secure	X				
	All bay door trim secure	X				
	Static ground strap (under coach) present	X				
	Wiper blades (check and/or replace)	X				
	4C - Glass and Mirrors	Passed	Needs Repair	Needs Replace	Complete	NOTES
	Drivers side windshield (free of chips/cracks)	X				
	Passenger side windshield (free of chips/cracks)	X				
	Windshield tint intact	X				
	Right side windows free of (chips/cracks/scratches)	X				
	Left side windows free of (chips/cracks/scratches)	X				
	Side mirrors intact (free of cracks/chips)		X			scratches on pass side / both mirrors have chrome bubbling

RO # :15096
MILEAGE: 34,943

COACH # : **4499**

3

4D - Roof Inspection		Passed	Needs Repair	Needs Replace	Complete	NOTES
Condition of sealant, gaskets, etc		X				
Condition of all antennas and domes		X				Local antenna deleted
Condition of roof air covers		n/a				
Condition of anemometers		X				
Condition of Spoiler		X				
Condition of Fantastic Vent covers		X				
Condition of slide-out awning toppers			X			fwd slide topper has minor frays, front and back of awning material
Cables and wires secure		X				
4G - Exterior Lights		Passed	Needs Repair	Needs Replace	Complete	NOTES
Exterior lights (back,front,side) operational		X				
Trailer light connections working properly		X				
5. BAYS						NOTES
Doors, Walls, Floor, & Ceiling C1		Passed	Needs Repair	Needs Replace	Complete	NOTES
Door lock and unlock		X				
Door handle operates correctly		X				
Door aligned and adjusted		X				
Door mechanisms (hinges, prop rods, operate properly)		X				
Gas struts function properly (if equipped)		X				
Bay light operation (light & switch good)		X				
Cosmetic condition of walls, floor, ceiling, cabinetry, etc.			X			lower plastic panel on bay door has a crack
120V outlets functional		n/a				
Doors, Walls, Floor, & Ceiling C2		Passed	Needs Repair	Needs Replace	Complete	NOTES
Door lock and unlock		X				
Door handle operates correctly		X				
Door aligned and adjusted		X				
Door mechanisms (hinges, prop rods, operate properly)		X				
Gas struts function properly (if equipped)		X				
Bay light operation (light & switch good)		n/a				
Cosmetic condition of walls, floor, ceiling, cabinetry, etc.		X				
120V outlets functional		X				

TECH(S) : Marc D

DATE : 10/2026

FEATHERLITE COACHES
PDI WORKSHEET

RO # :15096
MILEAGE: 34,943

COACH # : 4499

4

	Doors, Walls, Floor, & Ceiling C3	Passed	Needs Repair	Needs Replace	Complete	NOTES
	Door lock and unlock	X				
	Door handle operates correctly	X				
	Door aligned and adjusted	X				
	Door mechanisms (hinges, prop rods, operate properly)	X				
	Gas struts function properly (if equipped)	X				
	Bay light operation (light & switch good)	X				
	Cosmetic condition of walls, floor, ceiling, cabinetry, etc.		X			lower plastic panel on bay door has a crack
	120V outlets functional	X				
	Doors, Walls, Floor, & Ceiling C4	Passed	Needs Repair	Needs Replace	Complete	NOTES
	Door lock and unlock	X				
	Door handle operates correctly	X				
	Door aligned and adjusted	X				
	Door mechanisms (hinges, prop rods, operate properly)	X				
	Gas struts function properly (if equipped)	X				
	Bay light operation (light & switch good)	X				
	Cosmetic condition of walls, floor, ceiling, cabinetry, etc.		X			lower plastic panel on bay door has a crack
	120V outlets functional	X				
	5. BAYS (Continued)					NOTES
	Fuel Fill	Passed	Needs Repair	Needs Replace	Complete	
	Fuel door, caps, locks, hinges, etc in good shape	X				
	Doors, Walls, Floor, & Ceiling C5	Passed	Needs Repair	Needs Replace	Complete	NOTES
	Door lock and unlock	X				
	Door handle operates correctly	X				
	Door aligned and adjusted	X				
	Door mechanisms (hinges, prop rods, operate properly)	X				
	Gas struts function properly (if equipped)	X				
	Bay light operation (light & switch good)	X				
	Cosmetic condition of walls, floor, ceiling, cabinetry, etc.		X			lower plastic panel on bay door has a crack
	120V outlets functional	X				

RO # :15096
MILEAGE: 34,943

COACH # : 4499

5

	Doors, Walls, Floor, & Ceiling	Chassis Battery	Passed	Needs Repair	Needs Replace	Complete
	Door lock and unlock		X			
	Door handle operates correctly		X			
	Door aligned and adjusted		X			
	Door mechanisms (hinges, prop rods, operate properly)		X			
	Bay light operation (light & switch good)		X			
	Cosmetic condition of walls, floor, ceiling, cabinetry, etc.		X			
	120V outlets functional		X			
	Doors, Walls, Floor, & Ceiling	Side Engine	Passed	Needs Repair	Needs Replace	Complete
	Door lock and unlock		X			
	Door handle operates correctly		X			
	Door aligned and adjusted		X			
	Door mechanisms (hinges, prop rods, operate properly)		X			
	Bay light operation (light & switch good)		X			
	Cosmetic condition of walls, floor, ceiling, cabinetry, etc.		X			
	120V outlets functional		X			
	Doors, Walls, Floor, & Ceiling	Main Engine	Passed	Needs Repair	Needs Replace	Complete
	Door handle operates correctly		X			
	Door aligned and adjusted		X			
	Door mechanisms (hinges, prop rods, operate properly)		X			
	Gas struts function properly (if equipped)		X			
	Bay light operation (light & switch good)		X			
	Cosmetic condition of walls, floor, ceiling, cabinetry, etc.		X			

RO # :15096
MILEAGE: 34,943

COACH # : 4499

6

5. BAYS (Continued)						NOTES
Doors, Walls, Floor, & Ceiling	Radiator	Passed	Needs Repair	Needs Replace	Complete	
Door handle operates correctly		X				
Door aligned and adjusted		X				
Door mechanisms (hinges, prop rods, operate properly)		X				
Doors, Walls, Floor, & Ceiling	D5	Passed	Needs Repair	Needs Replace	Complete	NOTES
Door lock and unlock		X				
Door handle operates correctly		X				
Door aligned and adjusted		X				
Door mechanisms (hinges, prop rods, operate properly)		X				
Gas struts function properly (if equipped)		X				
Bay light operation (light & switch good)		X				
Cosmetic condition of walls, floor, ceiling, cabinetry, etc.		X				
120V outlets functional		X				
Fuel Fill		Passed	Needs Repair	Needs Replace	Complete	NOTES
Fuel door, caps, locks, hinges, etc in good shape		X				
Doors, Walls, Floor, & Ceiling	D4	Passed	Needs Repair	Needs Replace	Complete	NOTES
Door lock and unlock		X				
Door handle operates correctly		X				
Door aligned and adjusted		X				
Door mechanisms (hinges, prop rods, operate properly)		X				
Gas struts function properly (if equipped)		X				
Bay light operation (light & switch good)		X				
Cosmetic condition of walls, floor, ceiling, cabinetry, etc.		X				
120V outlets functional		n/a				
Doors, Walls, Floor, & Ceiling	D3	Passed	Needs Repair	Needs Replace	Complete	NOTES
Door lock and unlock		X				
Door handle operates correctly		X				
Doors aligned and adjusted		X				
Door mechanisms (hinges, prop rods, operate properly)		X				
Gas struts function properly (if equipped)		X				
Bay light operation (light & switch good)		X				
Cosmetic condition of walls, floor, ceiling, cabinetry, etc.		X				

TECH(S) : Marc D

DATE : 10/2026

FEATHERLITE COACHES
PDI WORKSHEET

RO # :15096
MILEAGE: 34,943

COACH # : **4499**

7

	120V outlets functional	n/a				
5. BAYS (Continued)						
	Doors, Walls, Floor, & Ceiling D2	Passed	Needs Repair	Needs Replace	Complete	NOTES
	Door lock and unlock	X				
	Door handle operates correctly	X				
	Door aligned and adjusted	X				
	Door mechanisms (hinges, prop rods, operate properly)	X				
	Gas struts function properly (if equipped)	X				
	Bay light operation (light & switch good)	n/a				
	Cosmetic condition of walls, floor, ceiling, cabinetry, etc.	X				
	120V outlets functional	X				
	Doors, Walls, Floor, & Ceiling D1	Passed	Needs Repair	Needs Replace	Complete	NOTES
	Door lock and unlock	X				
	Door handle operates correctly	X				
	Door aligned and adjusted	X				
	Door mechanisms (hinges, prop rods, operate properly)	X				
	Gas struts function properly (if equipped)	X				
	Bay light operation (light & switch good)	X				
	Cosmetic condition of walls, floor, ceiling, cabinetry, etc.	X				
	120V outlets functional	X				
	Driver Bay	Passed	Needs Repair	Needs Replace	Complete	NOTES
	Door lock and unlock	X				
	Door handle operates correctly	X				
	Door aligned and adjusted	X				
	Door mechanisms (hinges, prop rods, operate properly)	X				
	Bay light operation (light & switch good)	n/a				
	Cosmetic condition of walls, floor, ceiling, cabinetry, etc.	X				
	Tank and hoses - no cracks, leaks	X				
	Tank hold down apparatus	X				
	Fuses and wiring in good shape	X				
	Nose Bay	Passed	Needs Repair	Needs Replace	Complete	NOTES
	Opening mechanism operates correctly	X				
	Door aligned and adjusted	X				
	Door mechanisms (hinges, prop rods, operate properly)	X				
	Cosmetic condition of walls, floor, ceiling, etc.	X				

RO # :15096
MILEAGE: 34,943

COACH # : 4499

8

5. BAYS (Continued)						NOTES
Bay AV (Mechanical)	Location: C4	Passed	Needs Repair	Needs Replace	Complete	
TV motion good (if equipped)		n/a				
TV lock, cover, or protection acceptable		X				
Remote control storage present (velcro or drawer, etc)		X				
Components securely mounted (speakers, soundbar, Bluray, etc)		X				
Knobs, hinges, latches, controls, accessories		X				
Generator Bay Mechanical	Location: C3	Passed	Needs Repair	Needs Replace	Complete	NOTES
Generator making power		X				
All cooling fans operational		X				
Generator bay insulation in good condition		X				
Generator exhaust intact, no leaks		X				
Plumbing Bay Mechanical	Location: 5	Passed	Needs Repair	Needs Replace	Complete	NOTES
Shore cord operation with switch and remote		X	X			remotes inop, switch is good
Water hose reel operation		X				
Faucet functional		X				
Tank monitors functioning properly		X				
Bicolor controls lit and functional		X				
Knobs, hinges, latches, controls, accessories		X				
Water pump functional		X				
Gauges work properly		X				
120V outlets functional		X				
Bay Contents Mechanical (Various)		Passed	Needs Repair	Needs Replace	Complete	NOTES
Sliding storage trays operational		n/a				
Bay cooler/freezer operational (slides out, operates, lid, etc)		X				
Grill operation (slides out, operates, lid, etc)		n/a				
Bay chairs and holder in good shape		X				
Bay cooling fans operational		X				
Aux air compressor functions properly		X				

RO #:15096
MILEAGE: 34,943

COACH #: 4499

9

6. AWNINGS						NOTES
		Passed	Needs Repair	Needs Replace	Complete	
	Proper full function	X				
	Material in good condition		X			fwd slide out topper has minor frays on front and back
	Accent lighting complete/functional (if equipped)	n/a				
	Accent light controls functional (if equipped)	n/a				
	Wiring secure and tidy	X				
	Safety bouce or wind sensor operational	X				
	Remotes function, good batteries, etc	X				
7. Slide Outs						NOTES
		Passed	Needs Repair	Needs Replace	Complete	
	Proper operation in and out	X				
	Condition of seals, wipes, etc	X				
	Lock pins/paddles work properly	X				
	Floor clearance acceptable	X				
	Exterior cosmetic condition	X				
	Interior ceiling trim - no sagging, dragging, etc		X			both slide outs ceilings are loose where bulk head meets material
	Switches and/or knobs feel tight and solid	X				
8. AIR SYSTEM						NOTES
		Passed	Needs Repair	Needs Replace	Complete	
	Chassis - no leaks	X				
	Aux air - no leaks	X				
	Generator bags - no leaks	X				
	Driver seat - no leaks	X				
	Pocket doors - no leaks	X				electric

RO # :15096
MILEAGE: 34,943

COACH # : **4499**

10

9. VEHICLE INTERIOR						NOTES
9A - Cockpit (driver and passenger)	Passed	Needs Repair	Needs Replace	Complete		
Drivers seat (all elect/mech functions work)	X	X				No lumbar function but does have air ride feature
Electric horn	X					
Air horn	X					
Cockpit shades operate properly	X					
Dash radio working properly (AM,FM,CD,Nav)	X					
CB Radio function	X					
Automation system, dash control working	n/a					
All dash toggle switches working properly	X					
Knobs and controls present and in good condition	X					
Tell-Tale light for bay locks functioning properly		X				Stays on (common issue, sometimes only solvable by disabling)
All bicolor switches illuminated and working	X					
Step cover functional	X					
All cockpit lighting working correctly	X					
Entry steps & landing (flooring defects)	X					
Glove box in good condition	X					
Storage drawers, compartments, cup holders in good shape	X					
A/C vents in good condition	X					
Windshield washer function, operation and alignment	X					
Passenger seat (all elect / mech functions work)		X				foot rest is weak and does not go up when legs are on it
120V outlets functional	X					
9. VEHICLE INTERIOR (continued)						NOTES
9B - Salon & Galley	Passed	Needs Repair	Needs Replace	Complete		
Cabinets (hardware and adjustments)	X					
Cabinets (surface condition crack, chip, adheared)	X					
Cabinets (inside condition and appearance)	X					
Upholstery on couch (fadded, tears, stains, support)	X					
Folding / moving couch operation	X					
Upholstery on chairs (fadded, tears, stains, support)	X					
Carpet / Flooring (wear, stains, crack, chip, tear)	X					
Upholstery on dinette (fadded, tears, stains, support)	X					
Lighting / ceiling in salon (working & secure)	X					
Lighting in galley (working & secure)	X					
Counter tops (scratches, chips, dull, stains)	X					
Bicolor switches function properly	X					
Windows and screens function properly	X					
120V outlets functional	X					

TECH(S) : Marc D

DATE : 10/2026

FEATHERLITE COACHES
PDI WORKSHEET

RO # :15096
MILEAGE: 34,943

COACH #: 4499

11

	Material		X			slide out end caps and columns have loose material
	9C - Hall and Center Bath	Passed	Needs Repair	Needs Replace	Complete	NOTES
	Cabinets (hardware and adjustments)	X				
	Cabinet (surface condition crack,chip,adheared)	X				
	Cabinets (inside condition and appearance)	X				
	Mirrored walls (free of scratches)	X				
	Pocket doors operational	X				
	Bath door (hardware and operation)	X				
	Bath cabinets (surface condition crack,chip,adheared)	X				
	Bath counter tops (surface condition crack, chip)	X				
	Flooring (bathroom) (wear,stains,crack,chip,tear)	X				
	120V outlets functional	X				
	Flooring (hall) (wear,stains,crack,chip,tear)	X				
	Lighting / ceiling hall & bathroom	X				
	MDP panel cover (hardware and condition)	X				
	Fantastic vent operates properly	X				
	Shower door, walls & floor (no cracks,missing grout)	n/a				
	120V outlets functional	X				
	9. VEHICLE INTERIOR (continued)					NOTES
	9D - Stateroom	Passed	Needs Repair	Needs Replace	Complete	
	Cabinets (Surface condition crack,chip,adheared)	X				
	Cabinets (hardware and adjustments)	X				
	Cabinets (inside condition and appearance)	X				
	Bed operational (moveable/folding)	X				air bed fills and expels air as it should when pressing buttons
	Mattress condition (free of stains, support)	X				
	Flooring (wear, stains, crack, chip, tear)	X				
	Lighting / ceiling (all working & rope light secure)	X				
	Windows / screens function properly	X				
	Ceiling Fan Function	X				
	120V outlets functional	X				
	Material		x			slide out end caps and columns have loose material

RO #:15096
MILEAGE: 34,943

COACH #: 4499

12

[illegible]

RO # :15096
MILEAGE: 34,943

COACH # : 4499

13

10. PLUMBING					NOTES
	Passed	Needs Repair	Needs Replace	Complete	
Water pump pressure normal	X				
Visual inspection for leaks	X				
Water pump cycle time correct	X				
Auto fill operating properly	X				
Galley faucets operational	X				
Galley supply and drain line (dry and secure)	X				
Insta-Hot functional		X			hot side does not flow water and making funny noise
Center bath Faucets operational	X				
Center bath supply and drain lines (dry and secure)	X				
Center bath toilet flushes normal (both bi-color and hard button)	X				
Toilet hold water	X				
Shower faucet operational	X				
Shower drain free and clear	X				
Rear bath faucet operational	X				
Rear bath supply and drain lines (dry and secure)	X				
Rear bath toilet flushes normal	X				
Toilet holds water	X				
Tank monitors working properly	X				
Dump valves function properly, no leaks	X				
11. APPLIANCES					NOTES
	Passed	Needs Repair	Needs Replace	Complete	
Stove top (functions properly)	X				
Stove top (chips scratches)	X				
Microwave (functions properly, accessories present, cosmetic)	X				
Dishwasher (functions properly and no leaks)	n/a				
Outside cooktop / grill (functions properly, cosmetic)	n/a				
Washer / Dryer Check	X				
Refrigerator Functions (water, ice, cool, freeze)	X				

TECH(S) : Marc D

DATE : 10/2026

FEATHERLITE COACHES
PDI WORKSHEET

RO # :15096
MILEAGE: 34,943

COACH # : 4499

14

12. AUDIO / VISUAL					NOTES
12A - Component Function	Passed	Needs Repair	Needs Replace	Complete	
Salon TV (picture clear, sound clear, operation)	x				smart tv turns on with factory remote that is all
Salon TV (works with automation system)	n/a				
Galley TV (optional) (picture clear, sound clear)	n/a				
Galley TV (works with automation system)	n/a				
Stateroom TV (picture clear Sound clear)	x				smart tv turns on with factory remote that is all
Stateroom TV (works with automation system)	n/a				
Bay/outside TV (picture clear, sound clear)	x				smart tv turns on with factory remote that is all
Bay/outside TV (works with automation system)	n/a				
Forward surround sound operational		x			radio works but not hooked to the smart tv
Rear surround sound operational		x			radio works but not hooked to the smart tv
Aiphone operational	x				
Outside surround sound operational		x			radio works but not hooked to the smart tv
Sattelite reciever #1 (functioning properly)					
Sattelite reciever #2 (functioning properly)					
Sattelite reciever #3 (optional) (functioning properly)					
Park cable connection function					
12B - Automation System	Passed	Needs Repair	Needs Replace	Complete	NOTES
Salon system (functioning properly)		x			only functions lights and shades
Stateroom system (functioning properly)		x			only functions lights and shades
Outside system (functioning properly)	n/a				
Dash system (functioning properly)	n/a				
All functions operate from all screens and handhelds					
A. ISSUE					
B. ISSUE					
C. ISSUE					
D. ISSUE					
E. ISSUE					
F. ISSUE					
G. ISSUE					
H. ISSUE:					
I. ISSUE:					
J. ISSUE:					

[illegible]